

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD-20050AQ	Acura MDX, 01-06	Hood	Tong Yang	10/10A	60100S3VA91ZZ	AC1230110
HD56001Q	Acura MDX, 01-06	Hood	Cobra King	10/10A	60100S3VA91ZZ	AC1230110
S0809H000AS	Acura MDX, 01-06	Hood	Jui Li	10/10A	60100S3VA91ZZ	AC1230110
CV-20084AQ	Chevrolet HHR, 06-11	Hood	Tong Yang	04/11B	15838687	GM1230343
CVHR06HD1	Chevrolet HHR, 06-11	Hood	Gordon	04/11B	15838687	GM1230343
S0619H000AS	Chevrolet HHR, 06-11	Hood	Jui Li	04/11B	15838687	GM1230343
CVSR99FL1	Chevrolet Silverado, 99-02	Fender L	Gordon	01/11A	12479757	GM1240267
CVSR99FL1	Chevrolet Silverado, 99-02	Fender L	Gordon	01/11A	19168844	GM1240267
CVSR99FL1	Chevrolet Suburban, 00-06	Fender L	Gordon	01/11A	12479757	GM1240267
CVSR99FL1	Chevrolet Suburban, 00-06	Fender L	Gordon	01/11A	19168844	GM1240267
CVSR99FL1	Chevrolet Tahoe, 00-06	Fender L	Gordon	01/11A	12479757	GM1240267
CVSR99FL1	Chevrolet Tahoe, 00-06	Fender L	Gordon	01/11A	19168844	GM1240267
FDFO00HD1	Ford Focus, 00-04	Hood	Gordon	02/09A	YS4Z16612SA	FO1230188
DJ-CV96402-RH	Honda Civic, 96-98	Fender R	Da Juane	03/01A	60211S04A00ZZ	HO1241143
HD0700160-OR0C	Honda Civic, 96-98	Fender R	AP	03/01A	60211S04A00ZZ	HO1241143
HD-20016A-RH	Honda Civic, 96-98	Fender R	San Wanpum	03/01A	60211S04A00ZZ	HO1241143
HN-20025AQ	Hyundai Elantra, 04-05, to 10/27/04	Hood	Tong Yang	11/10A	664002D520	HY1230132
HN-20025AQ	Hyundai Elantra, 04-06	Hood	Tong Yang	11/10A	664002D521	HY1230132
HN2400090-000C	Hyundai Sonata, 06-08	Radiator Support	AP-Procom	11/10A	641010A000	HY1225150
HNS6484A	Hyundai Sonata, 06-08	Radiator Support	Auto Power	11/10A	641010A000	HY1225150
S0039H000AS	Saturn Sedan, 96-99	Hood	Jui Li	ALL	21110439	GM1230211
S0039H000AS	Saturn Wagon, 96-99	Hood	Jui Li	ALL	21110439	GM1230211
TA26001Q	Toyota Camry, 02-06	Hood	Cobra King	02/11A	53301AA060	TO1230186

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CV04132BBQ	Chevrolet Impala LS, 00-05, w/o appearance pkg	Bumper Cover, Front	TYG Products	10/07/03	12335971	GM1000633
CV04132BBQ	Chevrolet Impala LS, 01-04, w/o Appearance pkg	Bumper Cover, Front	TYG Products	10/07/03	12335506	GM1000633
FMC500-F05FLNEW	Ford Five Hundred SEL/Limited, 05-07	Bumper Cover, Front	Micro Rim	A1610	5G1Z17D957BAB	FO1000579
Y-FDBP059CA	Ford Mustang Deluxe/Premium, 05-09	Bumper Cover, Front	Y.C.C.	10/10A	5R3Z17D957AAA	FO1000574
HD-04117BBQ	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Tong Yang	05/11A	04715SDAA90ZZ	HO1100208
HD-04123BBQ	Honda Civic Hybrid, 04-05	Bumper Cover, Rear	Tong Yang	04/11A	04715S5AA91ZZ	HO1100217
HD-04153BBQ	Honda Civic Hybrid, 06-10	Bumper Cover, Rear	Tong Yang	01/11A	04715SNAA90ZZ	HO1100235
HD-04123BBQ	Honda Civic Sedan, 04-05	Bumper Cover, Rear	Tong Yang	04/11A	04715S5AA91ZZ	HO1100217
HD-04153BBQ	Honda Civic Sedan, 06-10, 1.8L eng	Bumper Cover, Rear	Tong Yang	01/11A	04715SNAA90ZZ	HO1100235
TY-05007VBQ	Toyota 4Runner Limited, 96-98, (6 cyl), Dark Gray	Panel, Valance	Tong Yang	01/11A	5391135130	TO1095176
TY-05007VBQ	Toyota 4Runner Limited, 96-98, (6 cyl), Dark Gray	Panel, Valance	Tong Yang	01/11A	5391135910	TO1095176
TY-04093BBQ	Toyota Camry, 97-99	Bumper Cover, Front	Tong Yang	02/11A	52119AA901	TO1000187
TY-04285BBQ	Toyota Matrix Base, 05-08	Bumper Cover, Front	Tong Yang	01/11A	5211902953	TO1000294
TY-04286BDQ	Toyota RAV-4, 06-08, w/wheel opng flare	Bumper Cover, Rear	Tong Yang	09/10A	5215942906	TO1100242

December, 2011*

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
20-5244-00-9	GMC Jimmy, 98-05, w/o fog lamps	Headlamp Assy, L	TYC Brother	03090910	16526227	GM2502174
20-5244-00-9	GMC Jimmy, 98-05, w/o fog lamps	Headlamp Assy, L	TYC Brother	12131010	16526227	GM2502174
20-5244-00-9	GMC Sonoma, 98-04, w/o fog lamps	Headlamp Assy, L	TYC Brother	03090910	16526227	GM2502174
20-5244-00-9	GMC Sonoma, 98-04, w/o fog lamps	Headlamp Assy, L	TYC Brother	12131010	16526227	GM2502174
20-6871-00-9	Jeep Compass, 07-10, w/o leveling system	Headlamp Assy, R	TYC Brother	10111010	5303842AB	CH2503176
20-6871-00-9	Jeep Grand Cherokee, 07-10, w/o leveling system	Headlamp Assy, R	TYC Brother	10111010	5303842AD	CH2503176
20-6871-00-9	Jeep Patriot, 07-10, w/o leveling system	Headlamp Assy, R	TYC Brother	10111010	5303842AB	CH2503176
20-6871-00-9	Jeep Patriot, 07-12, w/o leveling system	Headlamp Assy, R	TYC Brother	10111010	5303842AD	CH2503176

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from November 1, 2011 through November 30, 2011.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.