



**WEEKLY PARTS UPDATE
November 25, 2009**

[Report: P6]
Weekly

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BMW 5-Series Sedan, 04-08, Aluminum	Hood	BM-20014AQ	Taiwan Kai Yih	41617111385	BM1230116
BMW 5-Series Wagon, 06-08	Hood	BM-20014AQ	Taiwan Kai Yih	41617111385	BM1230116
Dodge Pickup, 02-06, (New Design), w/o dual rear wheels	Tailgate	DG9300770-000C	AP	55275969AB	CH1900121
Dodge Pickup, 07-08, w/o spoiler	Tailgate	DG9300770-000C	AP	55275969AB	CH1900121
Dodge Pickup, 09	Tailgate	DG9300770-000C	AP	55275969AB	CH1900121
Ford Focus, 08-09, w/grille	Fender L	FD-10167BQ-LH	Taiwan Kai Yih	8S4Z16006B	FO1240266
Ford Focus, 08-09, w/o grille	Fender L	FD-10167AQ-LH	Taiwan Kai Yih	8S4Z16006A	FO1240267
Honda Accord Coupe, 08-09	Fender L	HDAC08F11	Gordon	60260TE0A90ZZ	HO1240174
Honda Accord Coupe, 08-09	Fender L	S0631F100AS	Jui Li	60260TE0A90ZZ	HO1240174
Toyota Avalon, 05-09	Hood	TY5030150-000C	AP	53301AC040	TO1230202

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Malibu Base/LS/LT, 04-08	Bumper Cover, Rear	Y-GMBP326CA	Y.C.C.	12335940	GM1100679
Chevrolet Malibu LTZ, 06-07	Bumper Cover, Rear	Y-GMBP326CA	Y.C.C.	12335940	GM1100679
Honda Civic Hybrid, 06-09	Liner, Fender R	HDC1014KR-C	Great Bestcam	74101SNA00	HO1249134
Honda Civic Hybrid, 06-09	Liner, Fender L	HDC1014KL-C	Great Bestcam	74151SNA00	HO1248134
Honda Civic Sedan EX/EX Navi/LX, 06-09	Liner, Fender R	HDC1014KR-C	Great Bestcam	74101SNA00	HO1249134
Honda Civic Sedan EX/EX Navi/LX, 06-09	Liner, Fender L	HDC1014KL-C	Great Bestcam	74151SNA00	HO1248134
Honda Civic Sedan EX-L/EX-L Navi, 08-09	Liner, Fender R	HDC1014KR-C	Great Bestcam	74101SNA00	HO1249134
Honda Civic Sedan EX-L/EX-L Navi, 08-09	Liner, Fender L	HDC1014KL-C	Great Bestcam	74151SNA00	HO1248134
Honda Civic Sedan Si/Si Navi, 07-09	Liner, Fender R	HDC1014KR-C	Great Bestcam	74101SNA00	HO1249134
Honda Civic Sedan Si/Si Navi, 07-09	Liner, Fender L	HDC1014KL-C	Great Bestcam	74151SNA00	HO1248134
Nissan Sentra, 07-09, 2.0L eng	Bumper Cover, Rear	DS-04234BBQ	Tong Yang Plastics	85022ET30J	NI1100249
Nissan Sentra, 07-09, 2.0L eng	Bumper Cover, Rear	Y-DSBP224CA	Y.C.C.	85022ET30J	NI1100249
Toyota Corolla S/XRS, 09, w/spoiler holes	Bumper Cover, Front	TY-04329BEQ	Tong Yang Plastics	5211902989	TO1000342
Toyota Sequoia, 05-07	Liner, Fender R	TYS4014AR-C	Great Bestcam	538750C040	TO1251121
Toyota Sequoia, 05-07	Liner, Fender L	TYS4014AL-C	Great Bestcam	538760C040	TO1250121
Toyota Sienna, 98-03, paint to match	Bumper Cover, Rear	TY04182BAQ	TYG Products	5215908010B0	TO1100183
Volkswagen GTI Gen 5, 06-08	Bumper Cover, Front	Y-VWBP015CA	Y.C.C.	1K0807217AGRU	VW1000161
Volkswagen Jetta Gen 5, 05-09	Bumper Cover, Front	Y-VWBP015CA	Y.C.C.	1K0807217AGRU	VW1000161
Volkswagen Jetta Wagon, 09	Bumper Cover, Front	Y-VWBP015CA	Y.C.C.	1K0807217AGRU	VW1000161

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford Expedition, 07-09, w/black-out lamp assy	Headlamp Assy, L	20-6814-00-9	TYC Brother	7L1Z13008BB	FO2502226
Pontiac Vibe, 05-07	Headlamp Assy, R	336-1113R-AC1	DEPO	88973539	GM2503249

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BM-20016AQ	BMW 3-Series E46 Sedan/Wagon, 02-05	Hood	Taiwan Kai Yih	02/09A	41617042893	BM1230115
CR-802A	BMW 3-Series E46 Sedan/Wagon, 02-05	Hood	Chang Jung	02/09A	41617042893	BM1230115

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						



WEEKLY PARTS UPDATE November 25, 2009

[Report: P6]
Weekly

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from November 16, 2009 through November 20, 2009.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.